

On/Off Fan Clutch - Repair Kit Cross Reference



Horton Repair Kits	Legacy Horton Repair Kits	Repair Kits w/ Single Row Bearings
 1S-DP-S	Q995669, 995669, 994353, 994902, 995609	14-256-1, ABP N20 142561, FLT14-256-1, KQ795669, FCQ795669, FCR5669
 1S-DP	Q995568, 995550, 995530, 994348, 995607, 795568, 995568, 995606, 995635	14-256, 14-500, ABP N20 14256, ABP N20 14500, FLT14-256, FLT14-500, KQ795568, FCQ795568, FCR5568, 994985, 994900, 994347
 1S-DP-L	Q995575, 995575, 995567, 995608	

Note: Repair kits with extended fan studs available. Questions? Contact Horton at info@hortonwww.com

Two-Speed Fan Clutch - Repair Kit Cross Reference



Horton Repair Kits	Legacy Horton Repair Kits	Repair Kits w/ Single Row Bearings
 2S-DP-S	Q995617-S	24-256-1, ABP N20 242561, FLT24-256-1, KQ795669-2, FCQ795669-2, FCR5669-2
 2S-DP	Q995617, Q995582, 995543, 995547, 995617, 995582, 995559, 995557, 995591	24-256, ABP N20 24256, FLT24-256, KQ795582, FCQ795582, FCR5582, 995509, 995510
 2S-DP-L	Q995617-L	

Note: Repair kits with extended fan studs available. Questions? Contact Horton at info@hortonww.com