


DM Advantage[®] Repair Kits



Simplify your repair kit inventory!




- **Cover 95 percent of the DM Advantage on-highway fan clutch market with just four part numbers**
 - Less time to determine the correct part number
- **Dual fan pilot**
 - Reduce the number of SKUs for parts managers to stock
- **Pre-assembled components with rapid repair functionality**
 - Decreases repair time and complexity
- **DRAC bearings**
 - Provide highest durability
- **Tools required for repair included**
 - Improves user experience



ENGINEERED FOR:



On/Off Fan Clutch - Repair Kit Cross Reference

Horton Repair Kits	Legacy Horton Repair Kits	Repair Kits w/ Single Row Bearings
 <p>1S-DP-S</p>	Q995569, 995669, 994353, 994902, 995609	14-256-1, ABP N20 142561, FLT14-256-1, KQ795669, FCQ795669, FCR5669
 <p>1S-DP</p>	Q995568, 995550, 995530, 994348, 995607, 795568, 995568, 995606, 995635	14-256, 14-500, ABP N20 14256, ABP N20 14500, FLT14-256, FLT14-500, KQ795568, FCQ795568, FCR5568, 994985, 994900, 994347
 <p>1S-DP-L</p>	Q995575, 995575, 995567, 995608	

Two-Speed Fan Clutch - Repair Kit Cross Reference

Horton Repair Kits	Legacy Horton Repair Kits	Repair Kits w/ Single Row Bearings
 <p>2S-DP-S</p>	Q995617-S	24-256-1, ABP N20 242561, FLT24-256-1, KQ795669-2, FCQ795669-2, FCR5669-2
 <p>2S-DP</p>	Q995617, Q995582, 995543, 995547, 995617, 995582, 995559, 995557, 995591	24-256, ABP N20 24256, FLT24-256, KQ795582, FCQ795582, FCR5582, 995509, 995510
 <p>2S-DP-L</p>	Q995617-L	

Note: Repair kits with extended fan studs available. Questions? Contact Horton at info@hortonww.com

Committed to Your Ideal Airflow Solution

Horton® is the premium provider of engine cooling solutions worldwide. Our culture of innovation delivers high-performance products that last and services that help you meet your commitments. Trust Horton to help your products last longer, run quieter and consume less fuel.

Horton is IATF 16949, ISO 14001 and ISO 9001 certified.